

Copy 2 of 3

SAPC 12210
COPY 1 OF 1

SECRET

28 December 1956

To: WRSP(2)
Info: Headquarters

25X1A
From [REDACTED]

EXHIBIT NO. [REDACTED]
CLASS. [REDACTED]
DECLASSIFIED
DATE CHANGED TO: TS [REDACTED]
25X1A [REDACTED]
DATE [REDACTED]

I have received your report summarizing activities through November, 1956. The report covering System 1 was very good. In your future reports include System 3, System 5 and the Data Reduction equipment.

We have been flight-testing reels with metal hubs, going on the assumption that part of the trouble was being caused by warped hubs. So far we have about twenty hours of flight time which is inadequate to prove or disprove the value of going to metal hubs. We were greatly relieved to find that you now have the tape wrap problem reduced to the point of consuming one reel per month.

The solenoid is being added to the FAK list according to your instructions. Tru-Arc pliers are being shipped. I had understood that Haywood took Tru-Arc pliers with him.

The reel drive gear boxes must be lubricated periodically. We are presently using a combination of Moly Kote and silicone oil.

Several packages of assorted hardware for the recorders have been shipped.

The 6112 vacuum tubes will be checked for filament resistance before they are shipped as spares.

The patch cables for the data reduction equipment are being manufactured and will be shipped to you. There will be a set for each location - consisting of 65 cables. It is planned to furnish approximately \$25,000 worth of test equipment with System 4. This test equipment is just now being ordered. This will cause considerable hardship during the first phases of System 4 operation.

System 2 is presently undergoing evaluation tests between here and Washington, D. C. So far everything looks good.

We now have five MTS field engineers who have recently joined our staff. These men will be working with Systems 1, 2 and 3.

There is a change to your original employment agreement that must be signed and promptly returned. There is also a security agreement that must be signed and returned. In each case the signature must be made in triplicate and witnessed by [REDACTED] or the security chief.

25X1A9a

25X1A

Approved For Release 2000/09/01 : CIA-RDP81B00878R000200050009-2

SECRET

8R000200050099-2

Page 1 of 2

7-10
A-101
8-11

1-10
Kamb

Route to
Return to

8-11 11/57

SECRET

The witness should include his home address. These agreements contain the company name and should be retained in your possession no longer than 24 hours. Return these documents to the security chief, informing him that they contain the company name and should be promptly returned to this organization through proper channels. One set of each agreement is enclosed for [REDACTED] Only the security agreement is enclosed for [REDACTED]

25X1A


25X1A

25X1A

PWA:hcp

Encls: 2

1. 2 sets (in triplicate)
2. 3 sets (in triplicate)



58982

SECRET

MISSING PAGE

ORIGINAL DOCUMENT MISSING PAGE(S):

Enclosure